

ROSPA PLAY SAFETY INSPECTIONS 2021

ACTION PLAN – HAWARDEN

Item 18

PLAY AREA	EQUIPMENT	DESCRIPTION	FINDING NOTES	RISK LEVEL	TASK
1	Circular Drive	Minor issues, mostly low risk, with two areas medium risk, to be repaired .			
2	Gladstone Play Area	Minor issues, all at low risk, to be repaired or monitored.			
3	Gladstone Skate Park	Barriers	Height of the barriers should be at least 1200 mm and should be reached at a maximum distance of 300 mm from the front of the barrier	Low	Refer to manufacturer
4	Gary Speed	All low risk. Cable way requires dismantling inspection.			
5	Mancot Lane	Cable Way	Seat to cable clearance is less than the minimum permitted of 2100 mm for seating type runways (or 1800 where the moving parts of the traveller are enclosed).	Medium	Modify

6	Trueman's Hill	Mound	Covers void space	High risk area fenced and signed appropriate to requirement - monitor unauthorised access.	High	Monitor unauthorised access
7	Vickers Close	Minor issues, mostly low risk. Multiplay has no barriers to standing surface. Unit was installed prior to the publication of current standards. There is no requirement to make retrospective changes. [CURRENTLY UNDER CONSIDERATION VIA PUBLIC CONSULTATION]				
8	Yowley Road	Minor issues, mostly low risk. Some areas have medium risk with equipment requiring repair, monitoring or replacement parts.				

Full copies of each play area inspection report are available to members on request.